27


OUT61029

1967 JAN 25

P 252108Z JAN 67
FM NPIC WASHDC
TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB
RUCVAAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAAA/2D RTS BARKSDALE AFB LA
RUEPJS/DIA WASHDC
RUCIJRA/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF
RUCVAAA/2 AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 9693.

15TH AF (FOR DI), SAC (FOR DIM/GLASS LAMP/DOCR, DM 4)
2D AF (FOR DI).

- - 2. ORIGINAL NEGATIVE:
 - A. DENSITY AND RESOLUTION ARE GOOD.
- B. 9R SIDE: PLUS DENSITY OVALS ASSOCIATED WITH ROLLER CHATTER ARE PRESENT ON THE INBOARD AND OUTBOARD EDGES OF THE FIRST FEW FRAMES. A FOGGED AREA APPROXIMATELY Ø.5 INCH WIDE AND EXTENDING 4 INCHES INTO THE FORMAT FROM THE OUTBOARD EDGE IS PRESENT ON FRAMES 205, 207, 531, 847, 1018, 1065, 1918 AND 2053. DEGRADATION RESULTING FROM THIS FOGGING IS MINOR. ALSO A BAND OF FOG 5 INCHES WIDE AND EXTENDING ACROSS THE WIDTH OF THE FORMAT IS PRESENT IN FRAME 961. AN OPAQUE HEAT SPLICE IS PRESENT BETWEEN FRAMES 1144 AND 1145.
- C. 9L SIDE: TWO ROWS OF MINUS DENSITY DOTS SPACED 1.7 INCHES APART AND LOCATED 4.5 INCHES AND 6.5 INCHES FROM THE INBOARD ARE PRESENT ON THE FIRST 50 FRAMES. EDGE CRIMPING IS



21 207

Advance copy Sanitized



-2-

PRESENT ALONG THE OUTBOARD EDGE ON FRAMES 2081 THROUGH 2086.

- D. BOTH SIDES: FOG INDUCED BY EDGE STATIC AND ROLLER CHATTER IS PRESENT THROUGHOUT THE MISSION ON BOTH THE INBOARD AND OUTBOARD EDGES. IMAGE SMEARING ASSOCIATED WITH VEHICLE MANEUVERING WAS RECORDED ON SEVEN FRAMES.
 - 3. POSITIVE:
 - A. PI SUITABILITY IS GOOD.
 - B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURRED APPROXIMATELY 40 PERCENT OF THE MISSION.

 GP-1

SECRET

-END OF MESSAGE-